



Suggested Method to Cut Void Pieces to Fit and Eliminate Waste (for Slabs and Intermittent Footings):

1. Begin each row with full-size pieces.
2. Set the SlabVoid and/or filler pieces in line end-to-end.
3. Approaching the end, cross-cut pieces to fit shorter spaces, but do not use any piece less than 12" long.

If the space to be filled is less than 12":

- a. Take out the last full piece and cut it in half.
- b. Cut another full piece to fit and fill the remaining space with that longer piece.
- c. Use both cut-off pieces in the next run, thereby eliminating waste.